

Setting Up the USB Dock for the CPT-8000 Portable Data Terminal

To set up the USB Dock or Cable for the CPT-8000, follow the steps outlined below:

1. On Windows 7 computers, install “CP210x VCP Win7.exe”. On all other computers, install “CP210x VCP Win2K XP S2K3.exe” and accept all defaults.
2. Plug in the CPT-8000 USB dock into your PC and set your CPT-8000 into the dock. Now turn the CPT-8000 on. If any installation questions come up, accept all defaults.
3. On your PC, click on Start|Run and type the following: devmgmt.msc (then click Ok).
4. The Device Manager window will open. Click on the + sign next to Ports (COM & LPT).
5. Note which Com Port is next to CP210x USB to UART Bridge Controller (for example Com11).




Figure 1. Sample device management setup.

6. With this information you can now start up the communications program—“Data_Read.exe” and change the COM Port settings. You will now be able to transfer data from the barcode reader through the dock to your PC.




Figure 2. Data_Read.exe setup screen.